



A Brief Summary of the National River Restoration Science Synthesis (NRRSS)

Cliff Dahm

CALFED Science Program

cdahm@calwater.ca.gov



♦ Objectives:

- ♦ Characterize modern river restoration practices
- ♦ Determine the role of the scientific method and ecological knowledge in river restoration
- ♦ Identify the common elements of successful ecological restoration of streams and rivers
- ♦ Identify critical gaps in ecological knowledge that must be filled to facilitate more effective stream and river restoration

Phases:

1: Database creation

Collected project records for ~40,000 projects

Designed & constructed a database to merge all records into a common format


2: Interview surveys of ~ 400 project managers

3: Data analysis of restoration trends/effectiveness




- Project website: http://www.nrrss.umd.edu/NRRSS_INDEX.htm

National and Node Level Project Densities (n ~40,000) & Percentage of Projects Monitored by State



Distribution of Project Intents




Reported total = \$8 billion

Estimated total = \$15-17 billion

Number of Project Records

Common Monitoring Activities



The Kissimmee River Restoration Project

Cliff Dahm

CALFED Science Program


With Thanks to the South Florida Water Management District




Restoration of the Kissimmee River.

?

==



Applying Restoration Expectations.






An aerial photograph showing a straight canal (C-38) running vertically on the left side of the frame. To the right of the canal, a winding, meandering river channel is visible, surrounded by dense green vegetation. The landscape is a mix of green fields and forested areas. In the upper right, there's a small area of cleared land with some structures. The sky is visible at the top, showing some clouds.

**C-38 Canal and remnant Kissimmee River,
post channelization circa 1980**





Initial Restoration Segment



S-65B Explosive Demolition (June 19, 2000)



Photograph courtesy of Claudine Laabs

Anatomy of the Phase I Backfilling



Degraded
Spoil
Area

Backfilled
C-38


Remnant
River
Channel
(Micco Bluff Run)

Degraded
Spoil
Area

Remnant
River
Channel
(Oxbow 13)

Oxbow 13 - Micco Connector

February 9, 2001



Historic channel


Connector run


Backfilled canal

July 2001

Conceptual Model

Restoration → **Abiotic** → **Biotic**





Dissolved Oxygen at 1 Meter

60 Restoration Expectations

Testable Expectations of Changes

- **Hydrology - 6**
 - **Geomorphology - 2**
 - **Water Quality - 4**
 - **Vegetation - 10**
 - **Invertebrates - 11**
 - **Algae - 2**
 - **Herps - 2**
 - **Fish - 7**
 - **Birds - 11**
 - **Listed species - 5**
-

Dedicated Issue of Restoration Ecology
September 1995

Kissimmee River Restoration Evaluation Project

http://www.sfwmd.gov/portal/page/portal/pg_grp_sfwmd_watershed/pg_sfwmd_watershed_eval_program

- A Decade of Comprehensive Monitoring
- Wading Bird Populations (x5)
- Duck and Shorebirds Back
- River Bottom Organic Deposits Decreased by 71%
- Dissolved Oxygen Levels > 4 mg/L Continuously
- Largemouth Bass and Sunfishes from 38 to 64%

